SERVICE BULLETIN



No. : 0IVL20060060 Date : 2006-05-12

	Model	Factory	Factory Model	Suffix	Model No.	Factory	Factory Model	Suffix	(Mc	del No.		
		EKHQ	32LC2D-UD	ALUSLL	32LC2D	ENMX	32LC2D-UD	ALCA	LL 32	LC2D		
		ENMX	32LC2D-UD	ALUSLL	32LC2D	EKHQ	37LC2D-UD	ALUS	LL 37	LC2D		
		ENMX	37LC2D-UD	ALCALL	37LC2D	ENMX	37LC2D-UD	ALUS	LL 37	LC2D		
		EKHQ	42LC2D-UD	APUSLL	42LC2D	ENMX	42LC2D-UD	ACCL	LB 42	LC2D		
		ENMX	42LC2D-UD	APUSLL	42LC2D							
	D	Buyer N	lame Buyer Co	de Buye	er Name Bu	uyer Code	Buyer Name	Buye	r Code			
Buyer		LGEUS	US00000	1 LGE/	AI U:	S000002						
EFFECTIVE DATE		2006-	05-11		EFFECTI	VE FROM	(SERIAL NO.)	Al	1			
DATE												
	Subject	Sprin	Spring 2006 LCD/PDP Firmware upgrade 32LC2D-UD, 37LC2D-UD,									
42LC2D-UD												
No.	Loc No.	-	Before Change			After Change			Note	K-Code	Remark	
140.		Part No	Part No DESC./SPEC.			lo	DESC./SPEC.			i Couc	Roman	

Reason Of Change

Problem TVs:

2006 LCD, PDP, & MDPs that use the ARM CPU & Micronix Flash Memory.

Symptom:

During a specific date range the customer may turn on the TV and there will be no video or audio. The problem will first occur: Jun 20th, 2006, 14:03 ~ Jun 21st, 08:14. Then it repeats every 194 days.

Solution:

Temporary fix is a hard reset (unplug for a few seconds). New firmware is available as a permanent fix. The update needs to be done by a service center.

Models:

32LC2D, 37LC2D, 42LC2D, 42PC3DV, 42PC3DVA, 42PC3D, 50PC3D, 50PX2D, 50PX2DC.

Tools Required:

Computer

Null Modem Serial Cable

Tools Supplied:

Instructions

Firmware Files

DTVLab Update Software

Versions:

32LC2D-UD : Ver3.06.1 37LC2D-UD : Ver3.06.1 42LC2D-UD : Ver3.05.1

42PC3DV-UD(42PC3DVA-UD) : Ver3.06.1

42PC3D-UD : Ver3.07.1 50PC3D-UD : Ver3.07.1

50PX2D-UD(50PX2DC-UD) : Ver3.10.1

42PC3DV-UD, 42PC3DVA-UD: the same as S/W 50PX2D-UD, 50PX2DC-UD: the same as S/W

** FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

	NOTE(**) : IN	KEY-WORD CODE	
	Parts Set		
А	Original Early	Original or new parts may be used in early or late production sets.	1. To improve performance
	New Late	Use original parts until exhausted, then stock new parts.	2. To improve productivity
В	OriginalEarly	Original parts may be used in early production sets only. New parts may be used in early or late production sets.	3. To improve reliability
	New Late	Use original parts where possible, then stock new parts.	4. Change of material or dimension
С	Original Early	New parts only may be used in early or late production sets.	5. Addition
	New Late	Stock new parts.	6. Deletion
D	Original Early	Original parts only may be used in early production sets. New parts may be used in late production sets only.	7. Correction
	New Late	Stock original and new parts.	

CHIEF ENGINEER , approved Factory.